


Installing the USB driver for Windows XP

1. Connect a USB cable between your device and your computer. Windows will pop up a message telling you new hardware has been detected, similar to that shown to the right.




2. After a few seconds, the Found New Hardware Wizard will automatically open. Select "No, not at this time" as shown here, then click "Next".



3. Select "Install from a list or specific location (Advanced)", then click "Next".




4. Select "Browse" and a new window will pop open.



5. Browse to the install directory for the PMComm driver, then click “OK” to return to the previous window.



6. Click “Next”.



7. Windows will begin to install the driver then ask you to confirm compatibility. When you see this popup, click "Continue Anyway".



8. Installation is now complete. When you see a popup similar to this, click "Finish". Your USB port is ready to use. Your computer does not need to be re-booted.

